
Ipanema Bar habitat 🖄





▲ Safety and Care Advice

Product Details

Ipanema bar bistro set-yellow 846/9760

Ipanema bar bistro set-grey 933/4966

IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY.

• Keep children and animals away from the work area, small parts could choke if swallowed.

• Make sure you have enough space to layout the parts before starting.

• This product has been constructed to be used in the domestic environment only and not for commercial purposes.

• Assemble the item as close to its final position (in the same room) as possible.

• Assemble on a soft level surface to avoid damaging the unit or your floor.



• We do not recommend the use of power drill/drivers for inserting screws

as this could damage the unit. Only use hand screwdrivers.

• Parts of the assembly will be easier with 2 people.

• Dispose of all packaging carefully and responsibly.

Care and maintenance

• Only clean using a damp cloth and mild detergent. Do not use abrasive cleaners.

• Use a dry cloth to clean the product, furniture polish is not recommended.

• From time to time check that there are no loose screws, nuts or bolts. If there are please re-tighten.

• This product should not be discarded with household waste Take to your local authority waste disposal centre.


Additional Guidance


- Assemble all parts and bolts loosely during assembly, only once the product is complete should you fully tighten the bolts.
- Regularly check and ensure that all bolts and fittings are tightend properly.
- Age recommendation for upper bunk 18+
- Maximum user weight 50kg
- This product is compliant EN581

Registered office: Habitat Retail Limited, 489-499 Avebury Boulevard, Milton Keynes MK9 2NW.


Fittings


Bag 1

















Important: After all the parts are positioned, you can now fully tighten all screws fixed on previous steps.





IMPORTANT On a regular basis please check that the screws and fittings have not become loose as this could present a potential choke hazard.

Assembly is complete